

SQUARE PUNCH

- When punching a square hole there will be a slight burr on the back side of hole. If this is not permissible a sanding op may be added at a cost
- Square holes will be on center to the wire $\pm .015$ if center is implied
- Punch break out applies to all punched shapes (see punch break out)

